

DATE COLLECTED	CITY-TOWN	S/D	TRLR. PK.	INST.	SCHOOL	BOTTLED	MOTEL	REST	DAIRY	POOL	HOME	OTHER	DATE REC'D	DATE TESTED
6/14/71	MIAMI												6-19-71	6-19-71
NAME OF S/D OR LOCALITY BEING SAMPLED													NAME OR LOCATION OF WATER PLANT	
Hillsboro													Swimming Pool	
TYPE OF SAMPLE	ROUTINE	RE-CHECK	MAIN CLEARANCE	WELL SURVEY	OTHER	W. P. B.	APAL.	COUNTY	REMARKS					
LAB	JAX	MIAMI	TAMPA	PENSA.	ORL.			Hillsboro	Swimming Pool					
NAME AND MAILING ADDRESS OF PERSON/FIRM TO RECEIVE REPORT														
Campbell Ground Beach Tampa														

LAB. NO.	COLL. NO.	SAMPLING POINT	APPEAR-ANCE	CI RES'D	PH	LB. 48	BG 48	MPN 100 MLS	MF 100 MLS	NON-COLIFORM
#2058		Wet side lake - South						1600		
#2059		Wet side lake - North						1600		
		(I D 032)								

**WATER BACTERIOLOGY**

INTERPRETATIONS-RECOMMENDATIONS


REPORTS MAY BE DISCARDED AFTER SIX MONTHS

No. 142 (5)

Unsatisfactory for swimming

**POLLUTION CONTROL**

BY: *HAC* H. A. Cheatwood  
NAME: H. A. Cheatwood  
TITLE: Engineering Technician  
BUREAU OF SANITARY ENGINEERING



4/14

TYPE OF SUPPLY	CITY-TOWN	S/D	TALR. PK.	INST.	SCHOOL	BOTTLED	MOTEL	REST	DAIRY	POOL	HOME	OTHER
----------------	-----------	-----	-----------	-------	--------	---------	-------	------	-------	------	------	-------

NAME OF S/D OR LOCALITY BEING SAMPLED	NAME OR LOCATION OF WATER PLANT
---------------------------------------	---------------------------------


TYPE OF SAMPLE	ROUTINE	RE-CHECK <input checked="" type="checkbox"/>	MAIN CLEARANCE	WELL SURVEY	OTHER
----------------	---------	--	----------------	-------------	-------

LAB	JAX	MIAMI	TAMPA	TALLA.	PENSA.	ORL.	W. P. B.	APAL.	COUNTY
-----	-----	-------	-------	--------	--------	------	----------	-------	--------

NAME AND MAILING ADDRESS OF PERSON/FIRM TO RECEIVE REPORT	REMARKS
---	---------

[ H. A. Carroll  
(Beach)  
Tampa ]

Septuary Area



LAB. NO.	COLL. NO.	SAMPLING POINT	APPEAR- ANCE	CI RES'D	PH	LB. 48	BG 48	MPN 100 MLS	MF 100 MLS	NON-COLIFORM
#1	2060	North side beach						540		
#2	2061	South side beach						2400+		

**WATER BACTERIOLOGY** REPORTS MAY BE DISCARDED AFTER SIX MONTHS

INTERPRETATIONS-RECOMMENDATIONS

No. 1 (4) Satisfactory for swimming

No. 2 (5) Unsatisfactory for swimming

BY: *HAC* NAME: **H. A. Cheatwood** TITLE: **Engineering Technician** BUREAU OF SANITARY ENGINEERING

**POLLUTION CONTROL**  
**HILLSBOROUGH COUNTY**  
 APR 14 1971